

TERMOMETRY - TERMOMETRY - TERMOMETRY



OPIS

MODEL

Do wysokich temperatur – do pieczenia

0°C – 220°C,



550

0°C – 300°C, Timer



04 102

0°C – 300°C



04 103

0°C – 300°C, Timer



04 106

0°C – 120°C – bezprzewodowe



04 109

Kolor srebrny



04 190

50°C – 300°C



04 240